


Overhead Service Diagram



Notes:

1. An eyebolt must be installed when the riser does not go through the roof.
2. Risers more than 36" above the roofline must be properly anchored.
3. Smoke Detectors will be required and inspected inside the dwelling. Battery operated Smoke Detectors can be used, but their placement must be up to code.